0015



State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representativ	es Present During the Inspection:
OGM	April Abate Hydrologist
Company	Dennis Ware Controller
OGM	Steve Demczak Environmental Scientist III

Inspection Report

Permit Number:	C0070006			
Inspection Type:	COMPLETE			
Inspection Date:	Wednesday, November 12, 2008			
Start Date/Time:	11/12/2008 2:00:00 PM			
End Date/Time:	11/12/2008 4:00:00 PM			
Last Inspection:	Tuesday, October 14, 2008			

Inspector: Steve Demczak, Environmental Scientist III

Weather: Partly Cloudy, 40's

InspectionID Report Number: 1830

Accepted by: jhelfric

12/8/2008

Permitee: PLATEAU MINING CORP Operator: PLATEAU MINING CORP

Site: STAR POINT MINE

Address: PO BOX 30, HELPER UT 84526-0030

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Current Acreages

Total Permitted	8,919.91	
Total Disturbed	113.34	
Phase I	113.34	
Phase II		
Phase III		

Mineral Ownership

Other

Types of Operations ✓ Federal ✓ Underground ✓ State Surface County ☐ Loadout Processing

Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No violations were issied.

Inspector's Signature:

Steve Demczak, Environmental Scientist III

Date Wednesday, November 12, 2008

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070006 Inspection Type: COMPLETE

Inspection Date: Wednesday, November 12, 2008

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		\checkmark	
2.	Signs and Markers	✓			
3.	Topsoil	✓		✓	-
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments		✓		
4.c	Hydrologic Balance: Other Sediment Control Measures	✓		✓	
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations		✓		
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches		✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments		✓		
8.	Noncoal Waste	✓		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓			
10.	Slides and Other Damage	✓		✓	
11.	Contemporaneous Reclamation		✓		
12.	Backfilling And Grading	V		✓	
13.	Revegetation	V			
14.	Subsidence Control		✓		
15.	Cessation of Operations		✓		
16.8	a Roads: Construction, Maintenance, Surfacing		✓		
16.k	Roads: Drainage Controls		✓		
17.	Other Transportation Facilities		✓		
18.	Support Facilities, Utility Installations		✓		
19.	AVS Check	V			
20.	Air Quality Permit		V		
21.	Bonding and Insurance	V		V	
22.	Other	V			

Permit Number: C0070006 Inspection Type: COMPLETE

Inspection Date: Wednesday, November 12, 2008

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The Division conducted Phase II bond release at the Plateau Mine was conducted on October 29th and 30th. No major problems were noted in the inspection. Some weed control was advised in a remote Canyon were there is a fan breakout by the US Forest Service. The permit will expire on January 28, 2012.

3. Topsoil

All topsoil was used in reclamation of the site.

4.a Hydrologic Balance: Diversions

I spot-checked the diversion and they appeared to be stable. No signs of erosion was noticed during the inspection.

4.c Hydrologic Balance: Other Sediment Control Measures

The mine site is pocked to catch water from leaving. I did not notice any signs of water leaving the site. This method is also helpful to establish vegetation and the growth of vegetation.

4.d Hydrologic Balance: Water Monitoring

The water samples have been taken for the third quarter of 2008. The Division has not send a report to the permittee. The permittee has received a report from the Division for 1st, 2nd quarter of 2008.

8. Noncoal Waste

The site is clear of non-coal waste materials.

10. Slides and Other Damage

No slides were noticed during the inspection.

12. Backfilling And Grading

The mine site is completely backfilled and graded.

21. Bonding and Insurance

The bonding amount is \$3,118,400. The insurance will expire on October 1, 2008